



SGS-CSTC/Ningbo Branch/Oil, Gas & Chemicals Services  
1-3F, 4th Building,  
No. 1177 Lingyun Road  
Ningbo 315040, China  
Tel : (86-574) 87767006  
Fax: (86-574) 87777875

## Certificate of Inspection

Page no. : 1 of 2  
Date of Report: May 20, 2013/5/20

Client : Simagchem Corp  
Cargo : DIBUTHYL PHTHALATE  
Quantity : 50 DRUMS/ 10000 KGS  
Location : Zhejiang & Shanghai, China  
Date : April 12 & May 20, 2013  
Order no. : OGCNB1300550

This is to report that, at the request of the above client, we did attend on the date April 12, 2013, at the above mentioned premises for the purpose of sampling from drums said to contain: DIBUTHYL PHTHALATE at Zhejiang Factory, and on May 20, 2013 for the purpose of container loading supervision at Shanghai Warehouse, We report as follows:

**Packing:** The cargo is packed into blue plastic drums. total 50 drums.

### Sampling:

50 drums were selected for sampling by long glass pipe, total 2x500ml samples were obtained. The drum's lid was sealed by SGS logo adhesive tape after sampling.

The obtained samples were sent to SGS lab for testing and following result was obtained based on testing.

Property	Method	Results
Purity	GB/T11406-2005	99.56 % (m/m)

### Container Loading Supervision.

Before loading , we found 50 drums on site and the adhesive tape intact condition.  
Under the witness of our surveyor, All 50 drums Dibutyl Phthalate were loaded into 1x20' containers.

Container Number	Quantity	SGS Seal Number	Shipping Co. Seal Number
YMLU 3002947	50 Drums	002405	YMLT327331

The photograph report were attached

This inspection was based on our findings on the date above mentioned, date and place of inspection only and does not refer to any other matter.

SGS-CSTC Standards Technical Services Co., Ltd.

Authorized Signature  
Oil, Gas & Chemicals Services

*This document is issued by the Company under its General Conditions of Service accessible at [http://www.sgs.com/terms\\_and\\_conditions.htm](http://www.sgs.com/terms_and_conditions.htm). Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.*



# PHOTO REPORT

**Order No.** : OGCNB1300550  
**Client** : Simagchem Corp  
**Location** : Zhejiang Factory  
**Commodity** : DIBUTHYL PHTHALATE  
**Subject** : Sampling Photo  
On April 12, 2013

**SGS-CSTC Standards  
Technical Services Co., Ltd.**





## PHOTOGRAPHS OF REPORT OGCNB1300550



(Cargo Condition)



(Cargo Condition)



(Sampling)



(Obtained Sample)



(Sealing)



(Cargo Condition after Sealing)





# PHOTO REPORT

**Order No.** : OGCNB1300550  
**Client** : Simagchem Corp  
**Location** : Shanghai Warehouse  
**Commodity** : DIBUTHYL PHTHALATE  
**Subject** : Container Loading Supervision  
On May 20, 2013





## PHOTOGRAPHS OF REPORT OGCNB1300550



(Drum Condition)



(Tape Condition)



(Marking-1)



(Marking-2)



(Packing)



(Container Side Photo)



## PHOTOGRAPHS OF REPORT OGCNB1300550



(Container Door Side Photo)



(Empty Condition)



(Half Loading)



(Full Loading)



(After Sealing)



(Seal Photo)